

2001 Corvette: Service Bulletin: Lack of Power Following a Wide Open Throttle 4-2 or 3-2 Downshift and Subsequent 2-3 Upshift

Subject: Lack of Power Following a Wide Open Throttle 4-2 or 3-2 Downshift and Subsequent 2-3 Upshift (Reprogram PCM)

Source: Chevrolet Dealer Technical Service Bulletin

Number: 02-06-04-001

Date: January 2002

Models: 2001 Chevrolet Corvette with 5.7L Engine (VIN G – RPO LS1)

Condition: Some customers may comment that the engine lacks power following a wide open throttle downshift, either 3-2 or 4-2, followed by a wide open throttle 2-3 upshift.

Correction: A new service calibration is available for this condition. This calibration is available from Techline on the TIS 2000 version TIS 10/2001 data update or later. Reprogram the PCM with the new calibration.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/2001-corvette-service-bulletin-lack-of-power-following-a-wide-open-throttle-4-2-or-3-2-downshift-and-subsequent-2-3-upshift-391.html>