

1953 Corvette: Service Bulletin: Powerglide Transmission Slippage and Chatter in Automatic Low and Drive Range

Source: Chevrolet Service Technical Bulletin

Subject: Powerglide Transmission Slippage and Chatter in Automatic Low and Drive Range

Model and Year: 1953 Corvette

Bulletin Number: DR - 145

Section: VII

Section: June 24, 1953

TO: ALL CHEVROLET DEALERS

Slippage and chatter in Powerglide Transmission on medium and full throttle in both Automatic Low and Automatic Drive Ranges will exist when there is no oil drain hole in the Modulator Housing.

Oil seeping by the modulator piston builds up against diaphragm preventing the diaphragm spring from raising main line pressure and pressure in the Low Apply and clutch circuits under medium and full throttle acceleration.

The modulator body should have a drain hole 3/8" in diameter one inch directly below the center line of the modulator piston. Any housing found without the drain hole may be drilled in the dealership.

EL Harrig
Manager, Service and Mechanical Department

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=81>