

## Service Update

# N202315731 Wheel Casting with Exposed Porosity on Extra Set of Wheels



Release Date: March 2021

Revision: 00

**Attention:** This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

Make	Model	Model Year		RPO	Description
		From	To		
Chevrolet	Corvette	2020	2020		

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

<b>Condition</b>	Certain 2020 model year Chevrolet Corvette vehicles may have a condition where exposed porosity in wheel castings are larger than allowed and do not meet internal GM requirements. Vehicles in this field action are to have two sets of wheels inspected. The wheels on the vehicle are inspected under N202315730 and the extra wheels are inspected under this field action.
<b>Correction</b>	Dealers are to inspect the wheels and replace if necessary.

### Parts

Quantity	Part Name	Part No.
As Required	Wheel	84785086
As Required	Wheel	84785088
As Required	Wheel	84785085
As Required	Wheel	84785087
As Required	Wheel	84600213
As Required	Wheel	84723820
As Required	Wheel	84600212
As Required	Wheel	84723819
As Required	Wheel	23417380*
As Required	Wheel	84735859*
As Required	Wheel	84787695
As Required	Wheel	84787697

**\*This part is an Accessory part and is sold in a package qty of 8. Dealers should not be order through GMCCA. Dealers should order this part from their local ADI. This part will be reviewed and canceled daily.**

It is estimated that only 10% of involved vehicles will require parts replaced. **Due to the small number of vehicles anticipated that will need this fix and the limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.**

**Reminder:** Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

### Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9105363	Inspect 4 Road Wheels - No Further Action Required	0.2	ZFAT	N/A
9105364*	Replace First Road Wheel, Includes Inspection Add: Each Additional Wheel	0.5 0.3		

**\*Note:** This labor operation requires submittal via the Certified Service Mobile Toolbox (CSMT) App, in the Pre-Repair Authorization (PRA) section. The component name in the PRA is "Field Action" and the defect is "Wheel-N202315731". Please see bulletin 18-NA-306 for further details.

### Service Procedure

**This procedure applies to the extra set of wheels. Do not perform this procedure on wheels that are mounted on the vehicle.**

**Caution:** To avoid surface damage on wheels and wheel trim, do not use strong soaps, chemicals, abrasive polishes, cleaners, or brushes. Use only GM approved cleaners or the equivalent.

## Service Update

# N202315731 Wheel Casting with Exposed Porosity on Extra Set of Wheels



1. If required, clean the wheels using an appropriate cleaning solution. Use care to not damage the wheels with non-approved cleaners.
2. Thoroughly inspect the front side, back side, and rim of the wheels for porosity in the surface of the metal. Porosity examples are shown below in circles.

*The following photos show examples of the porosity condition covered by this bulletin.*

### Rim:



5754336

### Front Side of Spoke:



5754340

**Service Update**

**N202315731 Wheel Casting with Exposed Porosity on Extra Set of Wheels**



**Back Side of Spoke near Rim:**



5754354

**Back Side of Spoke near Rim:**




5754356

**Service Update**

**N202315731 Wheel Casting with Exposed Porosity on Extra Set of Wheels**



**Back Side of Spoke:**



5754359

**Back Side of Spoke:**



5754360

## Service Update

# N202315731 Wheel Casting with Exposed Porosity on Extra Set of Wheels



### Back Side of Spoke near Hub:



5754361

**Note:** Each wheel must be individually and thoroughly inspected to avoid invalid submissions. Do NOT automatically replace all four wheels on the vehicle.

3. If any of the above conditions are found, initiate the Pre-Repair Authorization (PRA) process for a wheel replacement authorization:

#### **US and Canadian Dealers:**

Need to submit a Pre-Authorization (PRA) in the Certified Service Mobile Toolbox (CSMT) app using the process in 18-NA-306. Dealers will still claim under the labor code 9105364 in the Warranty Information table. In the PRA, be sure to select the Component as "Wheel" and the Defect is "Field Action".

#### **Quebec Dealers:**

Take photos that clearly illustrates the porosity in the wheel. If multiple wheels are being replaced, identify the removal location from the vehicle on each wheel before taking the photo.

Attach photos to the GWM transaction and H-route for WSC agent approval.

#### **Middle East Regions:**

If any of the above conditions are found, initiate the Pre-Repair Authorization (PRA) process for a replacement wheel replacement authorization. Append pictures of the affected wheels to the PRA for your ATWM's review and approval.

**Note:** This bulletin is intended to address wheel casting porosity only. For any other warrantable cosmetic concerns discovered during the wheel inspection, refer to 18-NA-306 for replacement wheel authorization.

4. If required, install the customer's tire onto the new service wheel (or wheels). Refer to *Tire Dismounting and Mounting* in SI.
5. Once the new wheel replacement has been approved and the new wheel (or wheels) are mounted, the defective wheel (or wheels) need to be properly disposed of.

## Service Update

### N202315731 Wheel Casting with Exposed Porosity on Extra Set of Wheels



5754219

- Drill a 13mm (1/2 in.) hole completely through the rim barrel of the wheel.
- Recycle the unusable wheel with a reputable metal recycler.

#### Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin must be held and inspected/repared per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

#### Dealer Reports

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.

