

# Service Bulletin

File In Section: 08 - Body and Accessories

Bulletin No.: 05-08-42-009

Date: July, 2005



# **TECHNICAL**

Subject: Front Park/Turn Signal Bulb Intermittently Inoperative (Check Bulb Operation

and Replace Headlamp Wiring Harness, If Necessary)

Models: 2005-2006 Chevrolet Corvette

### Condition

Some customers may comment that the left or right or both front park/turn signal bulbs are inoperative. This condition may be intermittent and replacing the bulb may not correct it.

#### Cause

This condition may be due to a loss of contact between the base of the bulb and the socket.

## Correction

**Important:** Some early versions of the headlamp wiring harness have a section of harness that is not needed for this bulletin. Prior to installing harness to headlamp, disconnect and discard this section.

Check the bulb for correct operation off the vehicle by using a 12-volt power source. If the bulb is found to be inoperative, replace the bulb with a 5702 KA Phillips bulb, P/N 15233607. If the bulb is found to operate out of the socket, then the headlamp wiring harness should be replaced. Remove the headlamp assembly for access to the wiring harness (refer to the Front Headlamp Replacement in SI, Document ID #1507485).

### Parts Information

Part Number	Description	
19120497	Harness Assembly, Headlamp Wiring	

# Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
N9526*	Wiring Harness, Headlamp — Replace (One Side)	1.3 hrs
Add:	To Replace the Other Side	0.1 hr

\*This is a unique labor operation number for bulletin use only. This number will not be published in the Labor Time Guide.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

