

# 2014 - 2015 Corvette: Service Bulletin: Creak or Snap Noise Above Windshield from Removable Roof Lift Off Panel While Driving

---

**GM Bulletin No.:** #15-NA-016

**Date:** September 30, 2015

**SUBJECT:** Creak or Snap Noise Above Windshield from Removable Roof Lift Off Panel While Driving

**MODELS:** 2014 - 2015 Chevrolet Corvette

**CONDITION:** Some customers may comment on a creak or snap noise from the front of the removable roof lift off panel while driving. The noise is more predominant when ambient temperatures are high.

**CAUSE:** This may be caused by a stick-slip condition between the front latches against the strikers and the front locating pins to the locating cup in the strikers.

## #15-NA-016: Creak or Snap Noise Above Windshield from Removable Roof Lift Off Panel While Driving - (Sep 30, 2015)

**Subject:** Creak or Snap Noise Above Windshield from Removable Roof Lift Off Panel While Driving




**Attention:** This Bulletin also applies to any models that may be Export vehicles.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2014	2015			All	All

<b>Condition</b>	Some customers may comment on a creak or snap noise from the front of the removable roof lift off panel while driving. The noise is more predominant when ambient temperatures are high.
<b>Cause</b>	This may be caused by a stick-slip condition between the front latches against the strikers and the front locating pins to the locating cup in the strikers.


### Correction

If you encounter a vehicle with the above concern, replace both the front roof lift off panel strikers and both front locating pins. Refer to Roof Lift Off Panel/Window Front Striker Replacement and Removable Top Locating Pin Replacement in SI.



- (1) Example of a bad front locating pin.
- (2) Example of a good front locating pin.





- (1) Example of a bad striker.
- (2) Example of a good striker.

**Parts Information**

Qty	Description	Part Number
1	STRIKER, LF LIFT OFF PNL/WDO FRT	23374302
1	STRIKER, RF LIFT OFF PNL/WDO FRT	23374303
2	PIN ASM-R/TOP LOC	23412818

**Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
6080168*	Front Roof Lift Off Panel Striker and Locating Pin Replacement (Both Sides)	0.6 hr

\*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2014-2015-corvette-service-bulletin-creak-or-snap-noise-above-windshield-from-removable-roof-lift-off-panel-while-driving-1276.html>