

2000 Corvette: Service Bulletin: Exhaust Boom at 1500 RPM

Number: 00-06-05-002

Subject: Exhaust Boom at 1500 RPM (Install Spacers to Exhaust Hanger)

Model Year: 2000 Chevrolet Corvette

Built from S.O.P. through December, 1999

Condition

Some customers may comment on an exhaust boom heard inside the vehicle at 1500 RPM. Customers may also indicate an exhaust pipe outlet to fascia misalignment.

Correction

Install one 2 mm (.079 in) thick washer on each stud (2 per side), P/N 11505463, between the bumper bar and the muffler hanger, using the following procedure:

1. Raise the vehicle.
2. Remove the two nuts securing the left rear muffler hanger to the bumper reinforcement bar, then lower the exhaust.

3. Insert a washer on each muffler hanger mounting stud, as shown in the figure, then raise the exhaust.
4. Install the muffler hanger mounting nuts. Tighten

Tighten the nuts to 16 N·m (12 lb ft).

5. Repeat steps 2 -- 4 for the right rear muffler hanger.
6. Check alignment of the exhaust outlets, relative to the fascia.
7. If required, align the outlets by loosening the intermediate exhaust flange. Some adjustment is possible by applying upward or downward force on the exhaust pipe while the bolts are loose.
8. While holding the pipe, tighten the flange bolts. **Tighten**

Tighten the bolts to 50 N·m (37 lb ft).

Notice

Very little adjustment of the exhaust outlets to fascia exists by this method. If the exhaust outlets are misaligned due to improper contouring or bending of the exhaust pipes, replacement of the muffler is required. Refer to the Engine Exhaust sub-section of the 2000 Service Manual for replacement procedures.

9. Lower the vehicle.

Parts Information

Part Number	Description
11505463	Washer, Flat 2mm

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/2000-corvette->

[service-bulletin-exhaust-boom-at-1500-rpm-429.html](#)