

1990 - 1991 Corvette: Service Bulletin: Hard Start on Hot Restart / Increased Idle Speed

Subject: HARD STARTING DURING A HOT RESTART, INCREASE IN IDLE SPEEDS, AND IDLE FLUCTUATION (REPLACE MEM-CAL)

Model and Year: 1990-91 CHEVROLET CORVETTE WITH 5.7L ENGINE (VIN J - RPO LT5) AND MANUAL 6-SPEED TRANSMISSION (ML9)

Source: Chevrolet Service Bulletin

Bulletin Number: 47-65-03 - (01/24/1994)

CONDITION:

SOME OWNERS OF 1990 CORVETTES MAY COMMENT ON IDLE FLUCTUATION, INCREASE IN IDLE SPEED AFTER A HOT RESTART, AND AN INCREASE IN ENGINE SPEED DURING A VEHICLE COAST TO STOP WITH CLUTCH DEPRESSED.

SOME OWNERS OF 1991 CORVETTES MAY COMMENT ON A HARD STARTING CONDITION DURING A HOT RESTART.

CORRECTION:

THE CALIBRATIONS HAVE BEEN REFINED TO ADDRESS THESE CONCERNS. REPLACE THE MEM-CAL WITH THE DESIRED UNIT FROM THE CHARTS BELOW.

PART INFORMATION:

MODEL BROADCAST SCANNER PART BODY YEAR CODE I.D. NUMBER STYLE AXLE

1990 AYBK 3921 16163905 COUPE 3.45

1991 BFXB 3431 16193416 COUPE 3.45

PARTS ARE CURRENTLY AVAILABLE FROM GMSPO.

WARRANTY INFORMATION:

LABOR OPERATION: T0500 LABOR TIME: 0.5 HOUR

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer".

They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1990-1991-corvette-service-bulletin-hard-start-on-hot-restart-increased-idle-speed-484.html>