

## 2017 Corvette: Service Bulletin: SES Lamp Setting A P0106 And/or P0506

### #PIP5423: SES Lamp Setting A P0106 And/or P0506 - (Oct 3, 2016)

Brand:	Model:	Model Year:		VIN:		Engine:	Transmissi
		from	to	from	to		on:
Cadillac	Escalade	2015	2017	SOP	END	L86	All
Cadillac	CTS-V	2016	2017	SOP	END	Lt4	All
Chevrolet	Camaro	2016	2017	SOP	END	LT1	All
Chevrolet	Corvette	2017	2017	SOP	END	LT1, LT4	ALL
Chevrolet	Silverado	2014	2017	SOP	END	L83, L86, LV3	ALL
Chevrolet	Suburban	2015	2017	SOP	END	L83, L86	All
Chevrolet	Tahoe	2015	2017	SOP	END	L83, L86	ALL
GMC	Sierra	2014	2017	SOP	END	L83, L86, LV3	ALL
GMC	Yukon	2015	2017	SOP	END	L83, L86	ALL

*Involved Region or Country*

North America and .....

*Additional RPO/s:*

N/A

*Condition*

A vehicle may have a concern of the SES lamp with a P0106 and P0506.

*Cause*

This maybe caused by a broken valve spring

**Correction**

Replace the broken valve spring if the valve did not drop and cause block damage

Service Procedure;

Remove the valve cover and inspect for a broken valve spring.

If a broken valve spring is found inspect the intake manifold for a collapsed runner.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1315>