

2014 - 2017 Corvette: Service Bulletin: 17469 Fuel Leaks at the Primary Fuel Pump Module Flange

Special Coverage Adjustment

17469 Fuel Leaks at the Primary Fuel Pump Module Flange

Reference Number: N172131680

Release Date: April 2018

Condition: On some 2014 - 2017 model year Chevrolet Corvette vehicles, cracks on the top surface of the left fuel tank fuel pump module flange, may cause fuel odor, or a loss of fuel on the ground. A Check Engine lamp may illuminate if the fuel tank is less than half full.

Special Coverage Adjustment: This special coverage covers the condition described above for a period of 10 years or 120,000 miles (193,000 km), whichever occurs first, from the date the vehicle was originally placed in service, regardless of ownership.

For vehicles covered by Vehicle Service Contracts, all eligible claims with repair orders on or after April 18, 2018, are covered by this special coverage and must be submitted using the labor operation codes provided with this bulletin. Claims with repair orders prior to April 18, 2018, must be submitted to the Service Contract provider.

Vehicle owners or lessees who paid for repairs referenced in this Special Coverage (“Customers”) are eligible for reimbursement of their reasonable and customary expenses in accordance with the procedures specified below. The conditional right to reimbursement is provided by GM solely in the interest of customer satisfaction and is personal to Customers. Customers may not assign and GM does not consent to any assignment of any Customer’s right to submit reimbursement claims, or to receive reimbursement, or any other rights granted by this Special Coverage to any third party, including but not limited to service contract providers, and this Special Coverage is not intended to and does not confer any third party beneficiary, subrogation or contribution rights, or any other rights to reimbursement, against GM, whether in law, equity or otherwise, on any third parties.

Correction: Dealers are to replace the fuel pump module upon confirmation of the fuel pump module flange leak. The repairs will be made at no charge to the customer.

Complete document is attached.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1399>

