

# 2005 - 2006 Corvette: Service Bulletin: Information on Visual Brake Rotor Surface Cracking

**Service Bulletin #:** 05-05-23-007

**Date:** August 2005

**Subject:** Information on Visual Brake Rotor Surface Cracking

**Model(s):**

2005 - 2006 Chevrolet Corvette with Heavy Duty Brakes (RPO J55)

Attached below is the PDF document for this service bulletin.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved**

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=201>