

1969 Corvette: Engineering Service Letter: Speedometer Shaft Failure

Subject: Speedometer Shaft Failure

Model and Year: 1969 Corvette w/ 4-Speed Transmission

Date: NA

UPC XII - ELECTRIC AND INSTRUMENTS

E.S.L.

SPEEDOMETER SHAFT FAILURE - 1969 Corvette w/ 4-Speed Transmission (#1106)
(D.S.T.)

The failures have been attributed to kinking of the cable (transmission end) at time of installation. For interim 1969 Production, Engineering has released a new 5 inch longer cable and defined the routing to eliminate possibility of kinking.

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=24>