

2005 Corvette: GM TechLink: Service Information: Bose Speaker Rattle

According to a recent investigation, a door rattle concern in the 2005 Corvette may be caused by the Bose speaker rattling in the door panel.

To avoid unnecessarily replacing a speaker, perform the steps in bulletin 05-08-44-004 to determine if the listed repairs will correct the condition.

- Thanks to Art Spong and Ken Fischer, GM TechLink, April 2005

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=323>