

2005 Corvette: Service Bulletin: Information on the Operation of the Rear Compartment Lid/Hatch/Trunk Exterior Release Switch

Service Bulletin #: 05-08-66-002

Date: 3/21/05

Subject: Information on the Operation of the Rear Compartment Lid/Hatch/Trunk Exterior Release Switch

Model(s): 2005 Chevrolet Corvette

Customers and technicians need to be advised that the rear hatch/trunk release exterior switch located above the license plate will only operate if the FOB/Transmitter is within 1 meter (39 inches) from the rear hatch latch assembly.

Placing the FOB/Transmitter in the passenger compartment and attempting to open the rear hatch at the rear hatch exterior switch is not recommended.

The rear hatch latch assembly contains a proximity switch that requires the FOB/Transmitter to be within 1 meter (39 inches) in order for the exterior release switch to operate correctly.

Dealer technicians are unnecessarily replacing rear hatch system components; these components have been reviewed at the Warranty Parts Center (WPC) with No Trouble Found (NTF).

Hatch/Trunk Lid Release Operation

There are several ways to release the hatch/trunk lid. If your vehicle has an automatic transmission, the shift lever must be in PARK (P).

- (Hatch/Trunk): Press the hatch/trunk lid release button located on the instrument panel to the left of the steering wheel. The theft-deterrent alarm system must not be armed.
- (Hatch/Trunk): Press the hatch/trunk lid release button on the keyless access FOB/transmitter.
- Press the hatch/trunk exterior release button located on the rear of the hatch/trunk lid above the license plate, as long as you have the FOB/transmitter 1 meter (39 inches) from the latch assembly.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to

provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/2005-corvette-service-bulletin-information-on-the-operation-of-the-rear-compartment-lid-hatch-trunk-exterior-release-switch-362.html>