

1997 - 1999 Corvette: Service Bulletin: Squeak Type Noise From Leather Shift Boot when Shifting Gears

Subject: Squeak Type Noise From Leather Shift Boot when Shifting Gears (Replace Leather Shift Boot)

Source: Chevrolet Dealer Technical Service Bulletin

Number: 99-07-29-001

Models: 1997-99 Chevrolet Corvette with Manual Transmission (RPO MM6)

Condition

Some customers may comment that there is a squeak type noise coming from the leather shift boot when the gearshift lever is being moved.

Correction

Install a new leather shift boot assembly, P/N 10433159, using the Shift Control Boot Replacement procedure in the Manual Transmission - MM6 sub-section of the appropriate Service Manual.

Parts Information

Part Number	Description
10433159	Boot, Manual Transmission Shift Control

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1997-1999-corvette-service-bulletin-squeak-type-noise-from-leather-shift-boot-when-shifting-gears-382.html>