

# 1984 - 1986 Corvette: Service Bulletin: Power Seat Adjuster Excessive Movement

**Subject:** Power Seat Adjuster - Excessive Movement

**Model and Year:** 1984 - 1986 Corvette

**Source:** Chevrolet Dealer Service Bulletin

**Bulletin Number:** 86-117, Section 9 & 8B

**Date:** July, 1986

TO: ALL CHEVROLET DEALERS

Customer comments of excessive movement of seat adjusters on 1984 to 1986 Corvettes can be repaired by replacing the seat adjuster transmission assembly, P/N 10065222.

The condition is due to excessive gear clearances within the transmission assembly.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1984-1986-corvette-service-bulletin-power-seat-adjuster-excessive-movement-511.html>