

1995 Corvette: Service Bulletin: 3 - 2 Downshift Flare (Reflash Control Module)

Subject: 3 - 2 Downshift Flare (Reflash Control Module)

Model and Year: 1995 CHEVROLET CORVETTE WITH 4L60-E TRANSMISSION (RPO M30) AND 3.07 REAR AXLE RATIO BUILT BEFORE VIN BREAKPOINT 105682

Source: Chevrolet Dealer Service Bulletin

Bulletin Number: 57-71-02

REVISION: 02/03/95

THIS BULLETIN IS BEING REVISED TO CHANGE THE PARTS INFORMATION SECTION

CONDITION:

SOME OWNERS MAY EXPERIENCE A 3-2 DOWNSHIFT FLARE (ENGINE RPM INCREASE) BETWEEN 30 AND 60 MPH (48 AND 97 KM/H).

CAUSE:

TO ENCOMPASS VARIATION IN TRANSMISSION BUILDS.

CORRECTION:

REFLASH THE POWERTRAIN CONTROL MODULE WITH THE APPROPRIATE PART NUMBERS BELOW.

REFER TO YOUR SERVICE MANUAL FOR PROPER PROCEDURE.

PARTS INFORMATION:

PART # DESCRIPTION VERSION

16212471 FEDERAL NOVEMBER 16212461 EXPORT NOVEMBER

THIS NEW CALIBRATION IS AVAILABLE STARTING WITH THE NOVEMBER, 1994 CD UPDATE.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/1995-corvette-service-bulletin-3-2-downshift-flare-reflash-control-module-591.html>