

1965 Corvette: Engineering Service Letter: Dying on Quick Right Turns

Subject: Dying on Quick Right Turns

Model and Year: 1965 Corvettes Equipped with 365 HP - 327 CU IN Engine and Holley Carburetor

Source: Chevrolet Engineering Service Letter - Service Parts Change

Number: T.N. #7, Section VI

Date: June 30, 1965

Miscellaneous

Corvette with 365 HP - 327 CU IN Engine and Holley Carburetor Dying on Quick Right Turns

Condition can be corrected by installing the following Holley parts:

Floats: P/N 16R - 429A

Needles & Floats: P/N 18R - 96A

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=732>