

2005 - 2009 Corvette: Service Bulletin: Removable Top Squeaks When Stowed Away (Install Velcro)

#06-08-67-002A: Removable Top Squeaks When Stowed Away (Install Velcro) - (Jun 4, 2008)

Subject: Removable Top Squeaks When Stowed Away (Install Velcro®)

Models: 2005-2009 Chevrolet Corvette

Condition

Some customers may comment that the removable top squeaks when stowed away in the trunk.

Cause

This noise may be caused by the removable top rubbing on the removable top retainers.

Correction

Apply a piece of Velcro® (cloth side) to the removable top retainer.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2005-2009-corvette-service-bulletin-removable-top-squeaks-when-stowed-away-install-velcro-122.html>