2014 - 2016 Corvette: Service Bulletin: #16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 29, 2016)

#16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 29, 2016)

Loss of Radio Controls and/or HVAC Controls Subject: Model Year: Engine: Transmi Brand: Model: VIN: from from ssion: to t_0 A11 2014 2016 A11 Chevrol Corvette

et

Involved Region or Country North America and all N.A.Export

Regions

Condition Some customers may comment on a

loss of function with the

Radio/HVAC Interface Control Module (ICS) after ignition 'on'

cycle.

The condition will exhibit

intermittent characteristics, where the loss of function will discontinue after an additional ignition cycle. This may be caused by incorrect

This may be caused by incorrect

software/utility file level.

Cause

Correction

If you encounter a vehicle with the above concern, reprogram the radio

control with the latest software. Refer to *Radio Control Programming* and *Setup* in SI.

Online URL:

https://www.corvetteactioncenter.com/tech/knowledgebase/article/2014-2016-corvette-service-bulletin-16-na-188-loss-of-radio-controls-and-or-hvac-controls-jun-29-2016-1287.html