

2009 Corvette: Service Bulletin: Excessive Oil Consumption

Note: This bulletin only affects new-unsold in inventory Corvettes.

GM SERVICE AND PARTS OPERATIONS DCS 2223 URGENT DISTRIBUTE IMMEDIATELY

Date: March 10, 2009

Subject: 09043 Service Update Bulletin
For Inventory Vehicles Only
Excessive Oil Consumption – Incorrect Piston Ring –
Expires: September 30, 2009

Models: 2009 Chevrolet Corvette

To: Chevrolet Dealers

Attention: General Manager, New Vehicle Sales Manager,
Service Manager, Parts Manager and Warranty Administrator

General Motors is announcing Service Update Bulletin 09043 today. The total number of vehicles involved is 53.

This bulletin provides a service procedure to replace the engine on certain 2009 model year Corvette vehicles equipped with a 6.2 L V8 engine. Some of these vehicles may have one or more incorrect oil control rings installed in the engine. This could result in high oil consumption.

This service procedure should be completed on involved vehicles currently in dealership inventory as soon as possible but no later than September 30, 2009, at which time this bulletin will expire.

A vehicle VIN list sorted by BAC has been attached for your reference. If your BAC is not included on this list, you do not have any involved vehicles.

Service Information System (SI)
Bulletin 09043 will be available in SI on March 10, 2009.

GM Vehicle Inquiry System (GMVIS)
GMVIS information will be available on March 10, 2009.

Service Update Bulletin Information (SUB) Link

The Inventory VIN List will be available in the SUB link on March 11, 2009.

VIN Listing:

BAC VIN

111159 1G1YY25W295108097
111193 1G1YY26W895108281
111828 1G1YY26W395108172
112119 1G1YY26W395108396
112479 1G1YY25W595108157
112802 1G1YY25W895108234
112802 1G1YY25W995108419
112918 1G1YY36W395108176
112990 1G1YY26W195108476
113352 1G1YY25WX95108364
113645 1G1YY26W595111204
113710 1G1YY25W495111065
113801 1G1YY25W595111348
113867 1G1YY25WX95108140
113867 1G1YY26WX95108038
113914 1G1YY36W795108584
113974 1G1YY26W195108123
114196 1G1YY26W995111240
114428 1G1YY25W295108150
114549 1G1YY25W795108063
114659 1G1YY26W395111525
114745 1G1YY36W295111215
114770 1G1YY26W995108239
114859 1G1YY26W695111423
115090 1G1YY25WX95108168
115181 1G1YY26W295109197
115461 1G1YY26W195108137
116531 1G1YY25W495108182
132366 1G1YY25W395111414
158540 1G1YY25W395111218
158545 1G1YY26W095111532
159778 1G1YY26W195108378
162341 1G1YY25W795111531
163036 1G1YY36W495111426
163417 1G1YY25W795109147
164353 1G1YY25W295111260
164353 1G1YY26W895109186

166366 1G1YY26W195111216
168833 1G1YY36W595111418
173929 1G1YY25W495111020
185708 1G1YY26WX95111103
188691 1G1YY26WX95108220
192551 1G1YY25W195111511
194522 1G1YY36W195108421
206881 1G1YY36WX95108336
208631 1G1YY25W695108118
215125 1G1YY25WX95108297
216636 1G1YY36W195109150
221407 1G1YY26W995103865
230102 1G1YY25WX95108414
234369 1G1YY26W895111116

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserve

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/2009-corvette-service-bulletin-excessive-oil-consumption-136.html>