

# 2014 - 2017 Corvette: Service Bulletin: #PIP5467A: Repeat Codes P2096 and P2098

## #PIP5467A: Repeat Codes P2096 and P2098 - (Oct 4, 2017)

<b>Subject:</b>				Repeat Codes P2096 and P2098			
Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2014 - 2017					

<b><i>Involved Region or Country</i></b>	North America
<b><i>Condition</i></b>	<p>Customers may experience MIL Illumination with a repeat diagnostic codes P2096 P2098.</p> <p>These codes can be set when the operator drives in a digital manner when they tap the accelerator pedal (on - off - on -off) to maintain speed.</p>
<b><i>Cause</i></b>	Normal vehicle operating characteristic

### Correction

Engineering aware of the issue, at this time this is considered a normal vehicle operating characteristic

### Warranty Information

Labor Operation	Description	Labor Time
4081528*	Retrieve and Clear ECM Codes P2096 and P2098	0.3 hr
	*This is a unique Labor Operation for Bulletin use only.	
<i>Version</i>	2	
<i>Modified</i>	10/04/2017 to update correction	

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2014-2017-corvette-service-bulletin-pip5467a-repeat-codes-p2096-and-p2098-1383.html>