2020 Corvette: Service Bulletin: #20-NA-172: Remote Keyless Entry (RKE) System **Operational Change for Front Trunk Function**

2020 Corvette: #20-NA-172: Remote Keyless Entry (RKE) System Operational Change for Front Trunk Function - (Aug 27, 2020)

Subject: Remote Keyless Entry

(RKE) System

Operational Change for Front Trunk Function

Brand: Model: Model Year: Engine: VIN. **Transmis**

> from from to to

Chevrole Corvette 2020 2020 A11 A11

Involved Region or Country

Condition

Some customers may comment that the remote keyless function for the

front hood button does not work.

North America, Middle East

Cause The cause of the condition may be due

> to a design change to the Remote Keyless Entry (RKE) System button

sion:

function for the hood.

This change was implemented to reduce the chance of inadvertent

activation of the hood.

Customer Information

Inform the customer that in order to activate the hood with the Remote Keyless Entry (RKE) System, they must now press the hood button once and then press and hold the hood button down the second time to activate the hood release.

Failure to hold the button down on the second button press will not open the hood.

Please communicate the function change with the customer.

Parts Information

No parts are required for this repair.

Version 1

Modified Released August 27, 2020

Online URL:

https://www.corvetteactioncenter.com/tech/knowledgebase/article/2020-corvette-service-bulletin-20-na-172-remote-keyless-entry-rke-system-operational-change-for-front-trunk-function-1438.html