

# 1968 Corvette: Service Bulletin: Power Steering Bracket

**Subject:** Power Steering Bracket

**Model and Year:** 1968 Corvette with 427 cu. in. Engine

**Source:** Chevrolet Dealer Service Technical Bulletin

**Bulletin Number:** 68-T-46, Section IX

**Date:** Apr. 25, 1968

TO: AL CHEVROLET DEALERS

Some reports of power steering pump rackets cracking and/or breaking have been received on 1968 Corvettes equipped with 427 Cu. In. engine.

Effective in production since late March, a redesigned bracket has been used to correct the above condition.

In service when cracked or broken power steering pump brackets are encountered, they should be replaced with the following:

PART NO.	DESCRIPTION	QUANTITY
3946000	Brace	1
3946002	Bracket	1

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/1968-corvette-service-bulletin-power-steering-bracket-183.html>