

# Chevrolet Service Bulletin: Information on Proper Tire Pressure

**Service Bulletin #:** 00-00-90-002C

**Date:** August 2005

**Subject:** Information on Proper Tire Pressure

**Model(s):**

2006 and Prior Passenger Cars and Trucks (Including Saturn)

2006 and Prior HUMMER H2

2006 HUMMER H3

2005 - 2006 Saab 9-7X

This bulletin is being revised to add additional information regarding temperature and tire pressure. Please discard Corporate Bulletin Number 00-00-90-002B (Section 00 -- General Information)

Attached below is the PDF document for this service bulletin.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved**

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/chevrolet-service-bulletin-information-on-proper-tire-pressure-202.html>