

# 2005 Corvette: Service Bulletin: Creak or Popping Noise from Roof Near Windshield/"A" Pillar (Replace Plastic Guides In Roof Striker)

**Service Bulletin #:** 05-08-59-003A

**Date:** NA

**Subject:** Creak or Popping Noise from Roof Near Windshield/"A" Pillar (Replace Plastic Guides In Roof Striker)

**Model(s):** 2005 Chevrolet Corvette

## **Condition**

Some customers may comment on a creak or popping noise in the roof near the windshield area.

## **Cause**

The roof guide pins may have elongated the plastic guides.

## **Correction**

Replace the left and right plastic guide in the roof latch striker following the procedure below. (Note that the latch is on the headliner, next to the "A" pillar.)

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved**

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/2005-corvette-service-bulletin-creak-or-popping-noise-from-roof-near-windshield-a-pillar-replace-plastic-guides-in-roof-striker-361.html>