

# 1989 - 1990 Corvette: Service Bulletin: Improved Access to Inboard Seat Belt Buckle / New Extender

**Subject:** IMPROVED ACCESS TO INBOARD SEAT BELT BUCKLE/NEW EXTENDER

**Model and Year:** 1989-90 CORVETTE WITH AQ9 SEATS

**Source:** Chevrolet Service Bulletin

**Bulletin Number:** 90-291-10 - (06/22/1990)

## **CONDITION:**

To increase customer satisfaction a seat belt buckle extender has been released for service only, for use with AQ9 seats only.

## **CAUSE:**

With seats in full forward and up position buckle may not be of optimum length.

## **CORRECTION:**

If the customer should comment about this condition, a new seat belt extender, P/N 10175791 (Black only) is available from GMSPO at no charge to the customer.

**NOTE: WHEN ORDERING THIS PART, IT IS MANDATORY THAT THE CUSTOMERS NAME AND THE VEHICLE IDENTIFICATION NUMBER BE INCLUDED WITH THE ORDERING INFORMATION. THE ORDERING FORM FOR THIS PURPOSE IS ATTACHED TO THIS BULLETIN. PLEASE COPY LOCALLY.**



General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved**

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1989-1990-corvette-service-bulletin-improved-access-to-inboard-seat-belt-buckle-new-extender-506.html>