

1965 - 1966 Corvette: Service Bulletin: High Parking Brake Application Effort

Subject: High Parking Brake Application Effort

Model and Year: 1965 - 1966 Corvette

Source: Chevrolet Technical Service Bulletin

Bulletin No: TSB #66-59

Section: V

Date: May 4, 1966

TO: ALL CHEVROLET DEALERS

High parking brake application effort may be experienced on 1965-66 Corvettes due to the low mechanical advantage obtained from the relay lever.

To reduce application effort, a revised parking brake relay lever, with a higher mechanical advantage, was effective in production 4-1-66, Corvette Serial No. 6S118091. This relay lever, Part No. 3899399, is also used for service on 1965 and early 1966 Corvettes.

When installing the revised lever on 1965 and early 1966 models, reworking of the frame attaching bracket is necessary to provide rod clearance when the brake is fully released. The attaching bracket rework is shown in the attached sketch.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1045>