

2014 - 2015 Corvette: Service Bulletin: Creak or Snap Noise Above Windshield from Removable Roof Lift Off Panel While Driving

GM Bulletin No.: #15-NA-016

Date: September 30, 2015

SUBJECT: Creak or Snap Noise Above Windshield from Removable Roof Lift Off Panel While Driving

MODELS: 2014 - 2015 Chevrolet Corvette

CONDITION: Some customers may comment on a creak or snap noise from the front of the removable roof life off panel while driving. The noise is more predominant when ambient temperatures are high.

CAUSE: This may be caused by a stick-slip condition between the front latches against the strikers and the front locating pins to the locating cup in the strikers.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1276>