

2014 - 2016 Corvette: Service Bulletin: #16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 29, 2016)

#16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 29, 2016)

Subject:		Loss of Radio Controls and/or HVAC Controls					
Brand:	Model:	Model Year:		VIN:		Engine:	Transmissi
		from	to	from	to		on:
Chevrolet	Corvette	2014	2016			All	All

Involved Region or Country Condition

North America and all N.A.Export Regions
Some customers may comment on a loss of function with the Radio/HVAC Interface Control Module (ICS) after ignition 'on' cycle.

Cause

The condition will exhibit intermittent characteristics, where the loss of function will discontinue after an additional ignition cycle.
This may be caused by incorrect software/utility file level.

Correction

If you encounter a vehicle with the above concern, reprogram the radio control with the latest software. Refer to *Radio Control Programming and Setup* in SI.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1287>