

2007 - 2013 Corvette: Service Bulletin: 15682 Primary Tank Module Flange Fuel and Vapor Leaks

The attached service bulletin is below:

Special Coverage Adjustment

15682 Primary Tank Module Flange Fuel and Vapor Leaks

Reference Number: N150682

Release Date: July 2016

Condition

Some 2007 to 2009 model year Cadillac XLR and 2007 to 2013 model year Chevrolet Corvette vehicles may have a condition where a fuel odor is detected, fuel droplets appear below the left-hand fuel tank with fuel gauge level above 1/2, or a malfunction indicator lamp illuminates due to a leak path in the left-hand fuel pump module flange.

Special Coverage Adjustment

This special coverage covers the condition described above for a period of 10 years or 120,000 miles (193,000 km), whichever occurs first, from the date the vehicle was originally placed in service, regardless of ownership.

For vehicles covered by Vehicle Service Contracts, all eligible claims with repair orders on or after July 25, 2016, are covered by this special coverage and must be submitted using the labor operation codes provided with this bulletin. Claims with repair orders prior to July 25, 2016, must be submitted to the Service Contract provider.

Correction

Dealers are to replace the left hand fuel tank fuel pump module. The repairs will be made at no charge to the customer.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1293>