

2017 Corvette Z06: Service Bulletin: #PIP5485: Supercharger Whine Noise - (Mar 14, 2017)

#PIP5485: Supercharger Whine Noise - (Mar 14, 2017)

Subject:				Supercharger Whine Noise			
Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CTS-V	2017		All	All	6.2L LT4	All
Chevrolet	Camaro	2017		All	All	6.2L LT4	All
Chevrolet	Corvette	2017		All	All	6.2L LT4	All

<i>Involved Region or Country</i>	North America
<i>Additional RPO/s:</i>	LT4
<i>Condition</i>	Customer may comment on a whine noise from the engine bay.
<i>Cause</i>	Engineering is aware of this concern and have determined it will not impact durability and operation of the supercharger unit.

Correction

Condition will dissipate after 1200 - 1400 miles.

Warranty Information

Labor Operation	Description	Labor Time
4081598*	Diagnosis of Supercharger Whine Noise	0.3 hr.
	*This is a unique Labor Operation for Bulletin use only.	

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1334>