

# 2017 Corvette Z06: GM TechLink: Supercharger Idler Pulley Sounds

---

## 2017 Corvette Z06: Supercharger Idler Pulley Sounds

March 29, 2017

GM TechLink

A scraping or moaning sound may be heard from the supercharger idler pulley on some 2017 CTS-V, Corvette; and 2017 - 2018 Camaro models equipped with the supercharged 6.2L V8 engine (RPO LT4). The sound will be most noticeable when the engine is idling.

This condition has the following VIN breakpoints:

If the pulley sound is found, replace the idler pulley assembly. (Fig. 12)

**Fig. 12**

– *Thanks to Richard Renshaw*

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1362>