

2020 Corvette: Service Bulletin: #20-NA-172: Remote Keyless Entry (RKE) System Operational Change for Front Trunk Function

2020 Corvette: #20-NA-172: Remote Keyless Entry (RKE) System Operational Change for Front Trunk Function - (Aug 27, 2020)

Subject: Remote Keyless Entry (RKE)
System Operational Change for
Front Trunk Function

Brand:	Model:	Model Year:	VIN:	Engine:	Transmissi		
		from	to		on:		
Chevrolet	Corvette	2020	2020	—	—	All	All

***Involved Region or Country
Condition***

North America, Middle East
Some customers may comment that the remote keyless function for the front hood button does not work.

Cause

The cause of the condition may be due to a design change to the Remote Keyless Entry (RKE) System button function for the hood.

This change was implemented to reduce the chance of inadvertent activation of the hood.

Customer Information

Inform the customer that in order to activate the hood with the Remote Keyless Entry (RKE) System, they must now press the hood button once and then press and hold the hood button down the second time to activate the hood release.

Failure to hold the button down on the second button press will not open the hood.

Please communicate the function change with the customer.

Parts Information

No parts are required for this repair.

Version

1

Modified

Released August 27, 2020

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1438>