

# 2020 Corvette: Service Bulletin: #20-NA-217: Improved Electronic Limited Slip Differential (ELSD) Calibration - (Nov 10, 2020)

## 2020 Corvette: #20-NA-217: Improved Electronic Limited Slip Differential (ELSD) Calibration - (Nov 10, 2020)

**Subject:** Improved Electronic Limited Slip Differential (eLSD) Calibration

Brand:	Model:	Model Year:		Breakpoint Date:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT5	2020	2020	July 31, 2020	September 10, 2020	—	—
Chevrolet	Corvette			June 15, 2020	September 30, 2020		

**Involved Region or Country**

North America

**Additional Options (RPOs)**

Equipped with Electronic Limited Slip Differential (G96)

**Condition**

Some customers may comment on one or more of the following symptoms while driving the vehicle aggressively:

- Steering is too responsive on-center or during quick driving maneuvers.
- Inconsistent wheel slip on corner exit or pulling into traffic.
- Less stability on corner entry, especially with ESC/TCS turned off.

**Cause**

The cause of the condition may be an anomaly with the Electronic Limited Slip Differential (eLSD) software in the Brake System Control Module (BSCM).

**Correction**

Reprogram the BSCM with the latest

calibrations.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/2020-corvette-service-bulletin-20-na-217-improved-electronic-limited-slip-differential-elsd-calibration-nov-10-2020-1469.html>