

# 2020 - 2021 Corvette: Service Bulletin: #20-NA-123: Malfunction Indicator Lamp (MIL) Illuminated, DTCs U1961, U1983 Set - (Mar 8, 2021)

## #20-NA-123: Malfunction Indicator Lamp (MIL) Illuminated, DTCs U1961, U1983 Set - (Mar 8, 2021)

**Subject:** Malfunction Indicator Lamp (MIL) Illuminated, DTCs U1961, U1983 Set

Brand:	Model:	Model Year:		Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2021	2021	—	—	—	—
Cadillac	CT4	2020					
	CT5						
	Escalade Models	2021					
Chevrolet	Corvette	2020					
	Suburban	2021					
	Tahoe						
GMC	Yukon Models						

***Involved Region or Country***

North America, Middle East, GM Korea Company, Israel, Palestine

***Condition***

Some customers may comment that the Malfunction Indicator Lamp (MIL) is illuminated.

Technicians may find the following DTCs set:

- U1961 - Control Module Security Hardware Internal Malfunction
- U1983 - Serial Data Gateway Module Security Hardware Internal Malfunction

*Cause*

This condition may be caused by not clearing the DTCs and also allowing a sleep cycle after programming or serial data authentication configuration.

*Correction*

Clear the DTCs and allow the vehicle to go into sleep mode.

*Version*

3

*Modified*

Released June 02, 2020

November 13, 2020 – Added the Cadillac Escalade Models, Chevrolet Suburban, Tahoe and GMC Yukon Models and Warranty Information.

March 08, 2021 – Added the 2021 Buick Envision and 2021 MY to CT4, CT5 and Corvette.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1494>