

2024 Corvette Z06: Service Bulletin: #N232413030: Service Update - Lack of Auto Park Function - (Mar 25, 2024)

#N232413030: Service Update - Lack of Auto Park Function - (Mar 25, 2024)

Subject: N232413030 — Lack of Auto Park Function

Models: 2024 Chevrolet Corvette

Release Date: March 2024

Revision: 00

Attention:

This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

<i>Make</i>	<i>Model</i>	<i>Model Year</i>		<i>RPO</i>	<i>Description</i>
		<i>From</i>	<i>To</i>		
Chevrolet	Corvette	2024	2024	LT6	ENGINE - GAS, 8CYL, 5.5L

Involved vehicles are marked "Open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition

Certain 2024 model year Chevrolet Corvette vehicles, equipped with an 8-cylinder, 5.5 Liter engine, (RPO LT6), may have a condition in which the automatic shift to park function may not work under certain rare and unique conditions.

Correction

Dealers are to reprogram the Engine Control

Module (ECM).

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1523>