

1953 Corvette: Service Bulletin: Corvette Body Repair

Subject: Corvette Body Repair

Model Year: 1953 Corvette

Date: December 18, 1953

Bulletin Number: Z-22-194

Zone: #22 Louisville

With the increased distribution of the Chevrolet Corvette and the subsequent need for plastic body repair operations, the attached manual has been prepared to assist in making needed repairs properly and satisfactorily.

Since the plastic body is entirely new in the automotive field, considerable reluctance to tackle a repair job is evident. This reluctance can quickly be dispelled once a body man experiences his first repair operation as the repair procedures are simple and the paint refinishing procedure is the same as recommended for metal bodies.

The material covered in this manual is representative of the different types of damage that the body man may be called on to repair as well as a procedure for each repair. Repair kit, Part No. 3708438, contains all the necessary material for repairing these bodies.

We are sending you two copies of the repair manual.

Yours very truly,

A.E. Peet
Zone S&M Manager

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=175>