

1957 Corvette: Service Bulletin: Spark Plug Replacement

Model Year: 1957

Subject: 1957 Corvette Spark Plug Recommendations

Source: Chevrolet Technical Service Bulletin

Bulletin Number: DR #295

Section: VIy

Date: May 22, 1957

TO: ALL CHEVROLET DEALERS

Inasmuch as the greater percentage of Corvette engines are being operated in traffic congested areas AC-46 Spark Plugs are now being installed in production.

AC-46 entered production 4-9-57, Serial number E57S103268.

Corvette Engine Spark Plug Recommendations

Type	Type Driving	Part No.
AC-46	City	1559494
AC-44	Town & Country	1559492
C-43 Comm.	Heavy Duty & High Speed	5612002
C-42-1 Comm.	Road Racing	5612140

Above information will be inserted in the Corvette Operations Manual and will appear in next edition.

Corvette Engines with AC 46-5 Plugs

170 Corvettes were built during period 3-29 to 4-9-57 with AC 46-5 Plugs installed.

Serial # E57S-103098 to 103268.

These plugs should be changed to AC-46 due to spark plug boots not fitting the AC-46-5 plugs properly.

In cases where units operating in heavy traffic continue to oil foul spark plugs oil shedders should be installed.

E.L. Harvey
Manager, Service & Operations Dept.

ELH:mw

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/1957-corvette-service-bulletin-spark-plug-replacement-179.html>