

2007 Corvette: Service Bulletin: Information Regarding Automatic Transmission Shift Lock Control Function

Service Bulletin #: 03-07-30-043a

Date: May 2005

Subject: Information Regarding Automatic Transmission Shift Lock Control Function

Model(s):

2007 and Prior Passenger Cars and Trucks (Including Saturn)

2007 and Prior HUMMER H2, H3

2005 - 2007 Saab 9-7X

with Automatic Transmission

This bulletin is being revised to add models and model years. Please discard Corporate Bulletin Number 03-07-30-043 (Section 07 -- Transmission/Transaxle)

Attached below is the PDF document for this service bulletin.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/2007-corvette-service-bulletin-information-regarding-automatic-transmission-shift-lock-control-function-200.html>