

# 1953 - 1954 Corvette: Service Bulletin: Water Leaks - Corvette Doors

**Subject:** Water Leaks - Corvette Doors

**Source:** Chevrolet Service Bulletin

**Bulletin Number:** TSB #307, Section I

**Date:** September 1954

The complete bulletin consists of a 4 page PDF that is linked below:

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved.**

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=236>