

# 2005 Corvette: Service Bulletin: Check Gauges Light, Battery Voltage Low, Accessory Drive Belt Slipping or Missing (Install Crankshaft Balancer and Washer from WPC)

Check Gages Light, Battery Voltage Low, Accessory Drive Belt Slipping or Missing (Install Crankshaft Balancer and Washer from WPC)

**Bulletin Number: 05-06-01-001B**

**2005 Chevrolet Corvette with 6.0L Engine (VIN U - RPO LS2)**

**Built Prior to VIN Breakpoint 55111039**

## **Condition**

Some customers may comment on the Check Gages Light or the Battery Voltage Low indicator coming on. Additionally, some customers may comment on the accessory drive belt either slipping or being missing.

## **Cause**

The crankshaft balancer bolt may have become loose.

## **Correction**

Install a new crankshaft balancer pulley, washer and a new balancer pulley bolt using the following procedure.

## **Parts Information**

Part Number: 12557840

**Bolt, Crankshaft Harmonic Balancer**

Quantity: 1

Part Number: 12598247

**Washer, Crankshaft Balancer**

Quantity: 1

Part #: 12583637

**Balancer, Crankshaft Harmonic**

Quantity: 1

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved**

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=331>