

# 2002 - 2004 Corvette: Service Bulletin: Jingling Noise On Deceleration or Coast Down (Section and Replace Intermediate Exhaust)

**Service Bulletin #:** 04-06-05-006

**Date:** 3/30/05

**Subject:** Jingling Noise On Deceleration or Coast Down (Section and Replace Intermediate Exhaust)

**Model(s):** 2002 - 2004 Chevrolet Corvette

## **Condition**

Some customers may comment on an undesirable "jingle" or "jingling" type of noise when decelerating. The noise is similar to shaking a key ring. This condition is most prominent at the mid- to high-rpm range. This noise may also be noticed when driving next to a cement wall or other barrier that will deflect sound.

## **Cause**

This noise is coming from the "H" pipe area of the exhaust system. The center part of the "H" is formed by a crossover pipe connecting the left and right exhaust pipes. At this point, turbulence builds up in the exhaust system and may produce a jingle noise.

## **Correction**

A service section of the exhaust has been released that incorporates a revised crossover pipe. You will need to cut the original exhaust behind the catalytic converters as described in the procedure below.

10345549 Gasket, Exhaust --Rear flange 2

10276792 Clamp, 2 1/2" Exhaust 2

10352196 Pipe, Intermediate (Service Section) 1

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that

your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved**

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2002-2004-corvette-service-bulletin-jingling-noise-on-deceleration-or-coast-down-section-and-replace-intermediate-exhaust-428.html>