

1999 - 2000 Corvette: Service Bulletin: SMU - Deletion of Variable Effort Steering Description

Source: Chevrolet Dealer Service Bulletin

Number: 00-02-36-002A

Subject: SMU - Deletion of Variable Effort Steering Description

Model Year: 1999-2000

This bulletin is being revised to clarify that the Variable Effort Steering is not dealer adjustable using a scan tool. Please discard Corporate Bulletin Number 00-02-36-002 (02 -- Steering).

This bulletin is being issued to delete the information below that is found in the Variable Effort Steering Description in the Variable Effort Steering sub-section of the Service Manual.

Please delete:

The scan tool can be used to adjust the amount of steering effort, if the customer requests. The steering assist has (3) settings:

- Factory Calibration
- More Firm
- Less Firm

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=447>