

# 1963 Corvette: Service Bulletin - GM of Canada: Hood Lock Spring Assembly

**Model Year:** 1963 Corvette

**Subject:** Hood Lock Spring Assembly

**Source:** GM of Canada Service Bulletin

**Date:** July 15, 1963, Page 69

To correct a problem where the hood, if improperly latched, would come open on the above vehicles, a change was made in the hood lock assemblies to incorporate a new lock catch return spring.

The new spring, part #3841439, may be easily replaced on the existing lock spring assembly, as shown in 1963 Corvette Shop Manual Page 1-4, Figure 4, view "C".

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/1963-corvette-service-bulletin-gm-of-canada-hood-lock-spring-assembly-871.html>