

1964 Corvette: Service News: Corvette Hood Support Safety Hole

Subject: Corvette Hood Support Safety Hole

Model and Year: 1964 Corvette

Source: Chevrolet Service News

Page Number: 1

Date: January 1964, Volume 36, Number 1

Some early 1964 Corvettes have been built with the hood support safety hole through only one side of the hood support. This problem is easily corrected. First, raise the hood until it locks in the open position; then drill the 19/64" safety hole using the hole in the support lower half as a guide.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=898>