

1962 Corvette: Service Bulletin: Excessive Idle Speed

Subject: Excessive Idle Speed

Model and Year: 1962 Passenger Cars

Source: Chevrolet Technical Service Bulletin

Bulletin No: DR #522

Section: VII

Date: February 14, 1962

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=908>