

# 1956 Corvette: Service Bulletin: Crankcase Breather Assembly (Cap)

**Subject:** Crankcase Breather Assembly (Cap)  
**Model and Year:** 1956 Corvette and High Performance Passenger Cars  
**Source:** Chevrolet Technical Service Bulletin  
**Bulletin No:** DR #263  
**Section:** VI  
**Date:** September 28, 1956

TO: ALL CHEVROLET DEALERS

In cases where problems due to inadequate crankcase breaking is experienced on early 1956 Corvettes and High Performance Passenger Cars, the late type Crankcase Breather Assembly (Cap) should be installed.

The new Breather Assembly, with breather holes and gauze element, is the same as used in current passenger cars except that it is cadmium plated.

New Breather Assembly is now being used in production.

The early type (closed cap) is designed for reducing oil pull-over on units used for racing purposes.

## PARTS DATA

DESCRIPTION	TYPE	PART NO.
Crankcase Breather (Cap)	Open Breather Holes	* 1552940
Crankcase Breather (Cap)	Closed Breather Holes	1552719

\* Nonpublished part - must be ordered on Special Order through your Zone Parts and Accessory Department.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=974>