

# Customer Satisfaction Program

## 18096 Brake Deflector for Street Use Not Installed



Reference Number: N182154520

Release Date: April 2018  
Revision: 00

**Attention: This program is in effect until April 30, 2020**

Make	Model	Model Year		RPO	Description
		From	To		
Chevrolet	Corvette Z06	2019	2019		

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

<b>Condition</b>	Certain 2019 model year Chevrolet Corvette vehicles may have a condition in which the brake deflector for street use is missing.
<b>Correction</b>	Install the street deflector kit.

### Parts

Quantity	Part Name	Part No.
1	Front Brake Cooling Deflector Kit (W/O Front Rotor Cooling Ducts) (Contains both left and right deflectors and bolts)	22944235

It is estimated that only 348 involved vehicles will require parts replaced on this vehicle. **Due to the small number of vehicles anticipated that will need this fix and the limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.**

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.


### Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9103778	Install Street Use Front Brake Cooling Deflector Kit	0.6	ZFAT	N/A

### Service Procedure

# Customer Satisfaction Program

## 18096 Brake Deflector for Street Use Not Installed



3355427

1. Raise and support the vehicle. Refer to *Lifting and Jacking the Vehicle* in SI
2. Remove the Front Brake Rotor Cooling Deflector Fasteners (1) (Qty: 4)
3. Remove the Front Brake Rotor Cooling Deflector (2).
4. Install the new (Street Use) Front Brake Rotor Cooling Duct Deflector (2).
5. Apply blue Loc-Tite to the fasteners (1) and tighten to 4N-m (35 Lb-in).
6. Repeat on the other side of the vehicle.
7. Lower the vehicle.

### Dealer Responsibility

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this program must be held and inspected/repared per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Dealers are to service all vehicles subject to this program at no charge to customers, regardless of mileage, age of vehicle, or ownership, through April 30, 2020. Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the involved vehicle listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Program follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this program enters your vehicle inventory, or is in your facility for service through April 30, 2020, you must take the steps necessary to be sure the program correction has been made before selling or releasing the vehicle.

# Customer Satisfaction Program

## 18096 Brake Deflector for Street Use Not Installed



### Dealer Reports

For dealers with involved vehicles, a listing with involved vehicles has been prepared and will be provided to U.S. and Canadian dealers through the GM GlobalConnect Recall Reports, or sent directly to export dealers. The listing may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this program is a violation of law in several states/provinces/countries. Accordingly, you are urged to limit the use of this report to the follow-up necessary to complete this program.

### Courtesy Transportation

Courtesy transportation is available for customers whose vehicles are involved in a product program and still within the warranty coverage period. See General Motors Service Policies and Procedures Manual, Sections 1.4 and 6.1.10, for courtesy transportation program details.

### Customer Notification

USA & Canada - General Motors will notify customers of this program on their vehicle (see copy of customer letter included with this bulletin).

Export - Letters will be sent to known owners of record located within areas covered by the US National Traffic and Motor Vehicle Safety Act. For owners outside these areas, dealers should notify customers using the attached sample letter.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support  
Voluntary Technician  
Certification**

# Customer Satisfaction Program

## 18096 Brake Deflector for Street Use Not Installed



May 2018

This notice applies to your vehicle, **VIN:** \_\_\_\_\_

Dear General Motors Customer:

We have learned that your 2019 model year Chevrolet Corvette may have a condition in which the brake deflector for street use is missing.

Your satisfaction with your Chevrolet Corvette is very important to us, so we are announcing a program to prevent this condition or, if it has occurred, to fix it.

**What We Will Do:** Your GM dealer will install the new (Street Use) Front Brake Cooling Deflector Kit. This service will be performed for you at **no charge until April 30, 2020**. After that, any applicable warranty will apply.

**What You Should Do:** To limit any possible inconvenience, we recommend that you contact your dealer as soon as possible to schedule an appointment for this repair. By scheduling an appointment, your dealer can ensure that the necessary parts will be available on your scheduled appointment date.

If you have any questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-630-2438	1-800-833-2438
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

We sincerely regret any inconvenience or concern that this situation may cause you. We want you to know that we will do our best, throughout your ownership experience, to ensure that your Chevrolet Corvette provides you many miles of enjoyable driving.

Terry M. Inch  
Executive Director  
Global Connected Customer Experience

GM Recall: 18096