



HEATED OXYGEN SENSOR (BANK 1 SENSOR 1)

HEATED OXYGEN SENSOR (BANK 2 SENSOR 1)

TO INJ FUSES (DIAGRAM 1 OF 4)

A/C COMP RELAY 35

HOT AT ALL TIMES

HOT AT ALL TIMES

UNDERHOOD FUSE BLOCK

IGN 1 RELAY 44

ETC FUSE 9 10A

FUEL PUMP RELAY

