

# 1982 Corvette: Service Bulletin: Output Shaft Speedo Gear Clip Holes

**Subject:** Output Shaft Speedo Gear Clip Holes

**Model and Year:** 1982 THM 700-R4 Transmission

**Source:** Chevrolet Dealer Service Information Bulletin

**Bulletin No:** 82-I-126

**Section:** VIIc

**Date:** Sept., 1982

TO: ALL CHEVROLET DEALERS

Beginning in September, 1982, some 700-R4 transmission output shafts will be manufactured with two (2) speedo clip holes.

To properly install a speedo gear on these shafts, the clip holes must be referenced relative to the yoke spline end of the shaft as follows:

Corvette: Use the hole nearest the end of the shaft.

All Others: Use the hole farthest from the end of the shaft.

Chevrolet Motor Division  
General Motors Corporation

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1982-corvette-service-bulletin-output-shaft-speedo-gear-clip-holes-1114.html>